





# CTL

## CERTIFIED TESTING LABORATORIES, INC.

PICTURE NO.:

CLIENT: *Metrogreen*

DATE: *3/4/25*

PROJECT: *stone dust/utility sand*


TIME IN:

CONTRACTOR:

TIME OUT:

ARCHITECT/ENGINEER:

INSPECTOR: *Dale Joseph*



PICTURE OF: Sieve Analysis Graph

FLOOR:

LOCATION ON FLOOR:

DATE:

CTL SOF-35  
4/10/2020  
KD

THIS INSPECTION REPORT RELATES ONLY TO THE ITEMS INSPECTED/TESTED AS MENTIONED ABOVE.  
All reports are the confidential property of Clients, and information contained may not be published or reproduced, pending our written approval.  
140 Marbledale Road ° Tuckahoe, New York 10707 ° (718) 824-1616 ° Fax (914) 335-3089